



Figure 1

1/24/08



LEGEND:

- EW-1 EXTRACTION WELL
- IW-1 INJECTION WELL
- SS-1 CONFIRMATORY SOIL SAMPLING LOCATION
- CP-1 CAVITY MONITORING POINT
- INFILTRATION GALLERIES
- INJECTION PIPING
- EXTRACTION PIPING
- AREA OF EXCAVATION
- PROPERTY LINE



| FIGURE 15 | | | |
|--|-------|-------|---|
| EXISTING REMEDIATION SYSTEM LAYOUT | | | |
| HONEY BEAR MINI-MART | | | |
| 200 N. McKEAN STREET, KITTANNING, PENNSYLVANIA | | | |
| REMEDIAL ACTION PLAN | | | |
| DRAWN | DATE | PAGE | |
| BJL | 10/06 | | |
| CHECKED | DATE | SCALE | |
| SJG | 10/06 | NOTED | |
| | | | |
| | | | 611 SOUTH IRVINE AVENUE SHARON, PA 16146 |