



View of Valley Village from the eastern boundary looking west



View of the former railroad grade adjacent to the southern property boundary



Dispensers and convenience store



The UST cavity is located south of the dispensers and east of the store



Convenience store



View of the western boundary looking south



View of vacant lot and commercial property to the west



View from the western boundary looking east



Impacted soil is staged on the western property boundary and covered with plastic



A former septic system cleanout is located at the back of the building



View of a former railroad grade along the southern property boundary
and woodland further south



View of the rear of the building



Conduit from the UST system enters the northeast corner
of the building



Properties to the north and east of the site are residential



Valley Getaway Bar and Grill is across SR85 from the site



Properties to the north and west of the site are residential