Figure 1 – LUST Site Layout Aerial Photograph





Figure 2 - Spill Area & Nov. 2016 Soil Sample Locations (S1, S2 & S3)



| IPI AS   | SSOCIATES, INC.                     |                      | GEOTECHNICAL G           | & ENVIRONMENTAL SERVICES |
|----------|-------------------------------------|----------------------|--------------------------|--------------------------|
| Scale:   | 1" = 10.0 feet                      | Date:                | January 30, 2017         | By: JPI                  |
|          | EC                                  | l Sample Locatio     | ns - November 23, 2016   |                          |
| Location | : Blue Bell Sunoco, 889 Dekalb Pike | , Whitpain Township, | Montgomery Co., PA 19422 | FIG. I                   |

Figure 3 - Location of Previous Monitoring Wells (OW1, OW2, & OW3)




Figure 4 – Composite Soil Boring / Impact & Temporary Well Location Map

