

FACILITY PHOTOGRAPHS

United Refining Company
Kwik Fill # M-061
227 East Main Street
Bradford, Pennsylvania 16701

Direction of View:

West

Date Taken:

3-18-2013

Description:

View of station building,
and dispensers.



Direction of View:

Northeast

Date Taken:

3-18-2013

Description:

View of eastern property
boundary, along East
Main Street.



FACILITY PHOTOGRAPHS

United Refining Company
Kwik Fill # M-061
227 East Main Street
Bradford, Pennsylvania 16701

Direction of View:

East

Date Taken:

3-18-2013

Description:

View of residential properties beyond East Main Street.



Direction of View:

South

Date Taken:

3-18-2013

Description:

View of adjacent vacant property to the south.



FACILITY PHOTOGRAPHS

United Refining Company
Kwik Fill # M-061
227 East Main Street
Bradford, Pennsylvania 16701

Direction of View:

West

Date Taken:

3-18-2013

Description:

View of adjacent residential properties to the west of the facility (downgradient of the release).



Direction of View:

West

Date Taken:

3-18-2013

Description:

View of UST field located near southern property boundary.



FACILITY PHOTOGRAPHS

United Refining Company
Kwik Fill # M-061
227 East Main Street
Bradford, Pennsylvania 16701

Direction of View:

Northeast

Date Taken:

3-18-2013

Description:

View of commercial and residential properties beyond Mill Street.



Direction of View:

Northwest

Date Taken:

3-18-2013

Description:

View of the residential properties beyond Mill Street.



FACILITY PHOTOGRAPHS

United Refining Company
Kwik Fill # M-061
227 East Main Street
Bradford, Pennsylvania 16701

Direction of View:

North

Date Taken:

3-29-2013

Description:

View of retaining wall located along the southern property boundary.



Direction of View:

East

Date Taken:

3-29-2013

Description:

View of retaining wall located along the western property boundary.



FACILITY PHOTOGRAPHS

United Refining Company
Kwik Fill # M-061
227 East Main Street
Bradford, Pennsylvania 16701

Direction of View:

South

Date Taken:

9-11-2013

Description:

View of off-site
(Carlough) property
adjacent to the site.



Direction of View:

North

Date Taken:

6-5-2014

Description:

View of off-site
monitoring wells MW-17
through MW-19 in York
Street with residential
properties on either side.



FACILITY PHOTOGRAPHS

United Refining Company
Kwik Fill # M-061
227 East Main Street
Bradford, Pennsylvania 16701

Direction of View:

East

Date Taken:

12-18-2014

Description:

View of monitoring well MW-24 located on the off-site GE Dresser property along Mill Street.



Direction of View:

South

Date Taken:

10-24-2014

Description:

View of off-site Flood Plain Authority Property adjacent to Tunungwant Creek.

