


SOURCE: Figure 3 – Site Layout Map, December 2015 RAP, prepared by Letterle & Associates, Inc.

Figure 3 – Remedial System Layout



SOURCE: December 2015 RAP, prepared by Letterle & Associates, Inc.

Prepared By: Letterle & Associates 2022 Axemann Road, Suite 201 Bellefonte, PA 16823 P: 814-355-2241 F: 814-355-2410 www.letterleassociates.com Project Manager: Jed Hill Project Geologist: George Hunzeker, P.G. Prepared For: Kwik Fill M-90 1322 South 2nd Street Clearfield, PA 16830 Title: Figure 4 Soil Boring Location/Estimated Area of Impacted Soil Legend: Soil Boring Location Estimated Area of Impacted Property Boundary - Guiderails UST Vent Lines RAILS TO TRAILS Scale (ft.): 1" = 20' One Inch Equals Twenty Feet

Figure 4 – 2015 Soil Boring Locations

SOURCE: December 2015 RAP, prepared by Letterle & Associates, Inc.